# Escalhão Church



### **Description**

**Escalhão Church**, best known as *Igreja Matriz de Escalhão*, was built in the 16th century. Later in the 17th century there were added baroque elements to the existing church as well as the addition of lateral alterpieces.

The study focuses on the *Igreja Matriz de Escalhão*, exploring its architectural evolution and its significance within a transitional period in Portuguese architecture, described as "between renaissances." The objective is to analyze and understand how this church incorporates elements of the Manueline style—distinctive to Portugal during the Age of Discoveries—alongside features of the international Renaissance, blending local and global architectural trends. By comparing the *Igreja Matriz de Escalhão* with similar churches, the study aims to highlight its unique characteristics while situating it within the broader context of Portuguese architectural history.

### Modelling

José Araújo, Dionatan Bertelli, Tatiana Monteiro, Marcelo Odani

### **Cooperation Partnership**


Faculdade de Arquitectura da Universidade do Porto, Alma Mater Studorium - University of Bologna, Autonomous University of Barcelona


### **Used software**

Blender, Rhino 8, Agisoft Metashape, Darktable, Adobe Photoshop, Adobe Illustrator

### **Geo-coordinates**

Latitude 40.948778 Longitude -6.925917





## Selected sources




Fig. 45 Floor Plan Reconstruction (1973)

### **Drawn Reconstructions**

Floor Plan

Elevations

Sections

Comparison Analysis

### **Model Reconstruction**

Floor Plan

North Elevation

North Portal

South Elevation

South Portal

**West Elevation** 

West Portal

**East Elevation** 

3D Model Views

### **Scale of Uncertainty**

Drawn Reconstructions Floor Plan




### Variant: Floor Plan

### Working state

The drawn reconstruction of the floor plan is based on the previous drawing provided by the official source (SIPA - Information System for Architectural Heritage) dated on 1973, as well as on-site survey. Therefore, it was possible to prove the church was not orthogonally alined as the previous reconstruction shown, instead, the Escalhão Church has tilted angles and different dimensions than the one previously represented.





#### Reconstruction




Fig. 20 Floor Plan Drawn Reconstruction

#### Sources





Fig. 45 Floor Plan Reconstruction (1973)



**Fig. 65** Simplification of the previous reconstruction and measurements taken on the survey

## Drawn Reconstructions **Elevations**



### Variant: Elevation

### Working state


The elevation's drawings were based on the on-site survey and photograph records, once there was no previous information provided from official sources. It was possible to assume that interventions were made on the church after it was build, as some ornaments and windows do not represent the architectural vocabulary used in the 16th century.





#### Reconstruction








Fig. 14 North Elevation

Fig. 9 On-Site Survey




Fig. 15 South Elevation




Fig. 16 East and West Elevations




Fig. 13 North Portal Measurements





Fig. 7 Main Entrance of Escalhão Church




Fig. 8 Escalhão Church



Corte Longitudinal

Fig. 17 Section Cuts



No sources assigned




Fig. 21 Comparison between similar structures




Fig. 18 HAP\_painel 2.pdf




Fig. 19 Proportion's Study

Model Reconstruction Floor Plan



### Variant: Floor Plan

### Working state

The model reconstruction is based on the 1973's floor plan. After the On-site survey, the group realized element's alignment didn't match the drawn reconstruction found beforehand. As for the model, it was assumed the it's a representation of the object and didn't have to be the exact replica of what was built, for that, the priority was the orthogonal alignment and the proportion shown in the 1973's drawing.





#### Reconstruction




Fig. 44 Floor Plan Model Reconstruction

#### Sources





Fig. 45 Floor Plan Reconstruction (1973)



**Fig. 12** Measurements over Floor Plan's Reconstruction

## Model Reconstruction North Elevation



### Variant: North Elevation

### Working state

The north elevation reconstruction is based on the building's original state, disconsidering the existence of the main chapel and representing the windows used prior to the baroque intervention.







Fig. 51 North Elevation Reconstruction Model



Sources



Fig. 50 North Elevation Reconstruction Drawing

## Model Reconstruction North Portal



### Variant: North Portal

### Working state





### Reconstruction



Sources




Fig. 54 North Portal Model Reconstruction

Fig. 30 North Portal Reconstruction Drawing




Fig. 13 North Portal Measurements



Fig. 24 North Portal - Entablature Detail



Fig. 22 North Portal (1)



Fig. 25 North Portal, Column Base Detail



Fig. 23 North Portal - Column and Arch Detail




Fig. 26 North Portal



Fig. 27 North Portal, Column's Base Detail



Fig. 28 North Portal, Entablature Detail



Fig. 29 North Portal, Column Detail

### **Model Reconstruction** South Elevation




### Variant: South Elevation

### Working state

For the model's reconstruction, it was considered the project's original state, showing the windows used prior to the baroque intervention.

Sources










Fig. 49 South Elevation Reconstruction Model





Fig. 48 South Elevation Reconstruction Drawing










Fig. 42 South Portal Reconstruction Drawing



Fig. 40 2.01 South Portal



Fig. 38 2.02 South Portal Entablature



Fig. 39 2.03 South Portal's Column Base



Fig. 41 2.04 South Portal's Detail

## Model Reconstruction West Elevation



### Variant: West Elevation

### Working state





Sources

### Reconstruction



Fig. 47 West Facade Model Reconstrucion



Fig. 46 West Elevation Reconstruction Drawing




Fig. 7 Main Entrance of Escalhão Church


## Model Reconstruction West Portal



### Variant: West Portal

### Working state





### Reconstruction





Fig. 37 3. West Portal Model Reconstruction




Fig. 36 West Portal Reconstruction Drawing



Fig. 31 3.01\_West Portal Detail



Fig. 32 3.02\_West Portal Detail



Fig. 33 3.03\_West Portal Detail



Fig. 34 3.04\_West Portal Detail



**Fig. 35** 3.04\_West Portal

# **Decisions** Model Reconstruction **East Elevation** Variant: East Elevation Working state **Evaluation** Used in the result: Drawn Reconstruction Unknown Geometry Surface structure Coloring Reconstruction Sources

Fig. 53 East Elevation Model Reconstruction



Fig. 52 East Elevation Reconstruction Drawing



No reconstructions assigned

No sources assigned



Alçado Norte

Fig. 14 North Elevation



Alçado Sul

Fig. 15 South Elevation




Fig. 16 East and West Elevations




Fig. 17 Section Cuts

## Final renderings




Fig. 18 HAP\_painel 2.pdf

# Final renderings




Fig. 19 Proportion's Study




Fig. 20 Floor Plan Drawn Reconstruction




Fig. 21 Comparison between similar structures



Fig. 37 3. West Portal Model Reconstruction



Fig. 43 South Portal Model Reconstruction

## Final renderings




Fig. 44 Floor Plan Model Reconstruction



Fig. 47 West Facade Model Reconstrucion




Fig. 49 South Elevation Reconstruction Model

## Final renderings




Fig. 51 North Elevation Reconstruction Model




Fig. 53 East Elevation Model Reconstruction



Fig. 54 North Portal Model Reconstruction




Fig. 6 Floor Plan (1973)

**Type** Drawn Reconstruction

**Description** Reconstruction Drawing of the

Floor Plan, found on SIPA -Sistema de Informação do Património Arquitectónico (Information System for Architectural Heritage)

**Author** Unknown

**Archive** 

Signature

Copyright




Fig. 7 Main Entrance of Escalhão Church

Type Photograph Used in:

Description Drawn Reconstructions

Author Elevations

Archive Porto City Council's Archive Model Reconstruction

Signature West Elevation

Copyright



Fig. 8 Escalhão Church

**Type** Photograph

**Description** Main Chapel and façade of

Escalhão Church

**Author** Guilherme Bonfim Barreiros

**Archive** Porto City Council's Archive

Signature

Copyright

Used in:

**Drawn Reconstructions** 

Elevations




Fig. 9 On-Site Survey

**Type** Survey drawing

**Description** Hand drawing from the

measurements taken on the site

survey

**Author** 

**Archive** 

Signature

Copyright

Used in:

**Drawn Reconstructions** 

Elevations




Fig. 11 Element's Alignment over Picture

**Type** Photograph

Description

**Author** 

**Archive** 

Signature

Copyright




Fig. 12 Measurements over Floor Plan's Reconstruction

**Type** Survey drawing **Used in:** 

**Description** On-site survey, measuring the <u>Model Reconstruction</u>

elements according to the

existent Floor Plan

Floor Plan

**Author** 

**Archive** 

Signature

Copyright




Fig. 13 North Portal Measurements

Signature

Copyright

**Type** Contemporary drawing / sketch **Used in:** 

**Description** Digital sketch containing the <u>Drawn Reconstructions</u>

measurements from the North

Portal

**Author** Model Reconstruction

Archive

IDOVIR 52

North Portal




Fig. 22 North Portal (1)

**Type** Photograph

Description

Author

**Archive** 

Signature

Copyright

Used in:

**Model Reconstruction** 

North Portal



Fig. 23 North Portal - Column and Arch Detail

Type Photograph Used in:

**Description** Model Reconstruction

.....

**Author** North Portal

Archive

Copyright

Signature



Fig. 24 North Portal - Entablature Detail

**Type** Photograph

Description

Author

**Archive** 

Signature

Copyright

Used in:

**Model Reconstruction** 

North Portal



Fig. 25 North Portal, Column Base Detail

**Type** Photograph

Description

Author

**Archive** 

Signature

Copyright

Used in:

**Model Reconstruction** 

North Portal




Fig. 26 North Portal

**Archive** 

Signature

Type Photograph Used in:

**Description** Model Reconstruction

**Author** North Portal

**NOTHIT OF CA** 

Copyright



Fig. 27 North Portal, Column's Base Detail

**Type** Photograph

Description

**Author** 

**Archive** 

Signature

Copyright

Used in:

**Model Reconstruction** 

North Portal



Fig. 28 North Portal, Entablature Detail

**Type** Photograph

Description

**Author** 

**Archive** 

Signature

Copyright

Used in:

**Model Reconstruction** 

North Portal



Fig. 29 North Portal, Column Detail

**Type** Photograph

Description

**Author** 

**Archive** 

Signature

Copyright

Used in:

**Model Reconstruction** 

North Portal




Fig. 30 North Portal Reconstruction Drawing

**Type** Drawn Reconstruction

**Description** Drawn reconstruction based on

photograph records and on-site

survey

**Author** 

**Archive** 

Signature

Copyright

Used in:

**Model Reconstruction** 

North Portal



Fig. 31 3.01\_West Portal Detail

**Type** Photograph

**Description** Column's Base

Author

**Archive** 

Signature

Copyright

Used in:

**Model Reconstruction** 

West Portal



Fig. 32 3.02\_West Portal Detail

**Type** Photograph

Description

Author

**Archive** 

Signature

Copyright

Used in:

**Model Reconstruction** 

West Portal



Fig. 33 3.03\_West Portal Detail

**Type** Photograph

Description

Author

**Archive** 

Signature

Copyright

Used in:

**Model Reconstruction** 

West Portal



Fig. 34 3.04\_West Portal Detail

**Type** Photograph

Description

**Author** 

**Archive** 

Signature

Copyright

Used in:

**Model Reconstruction** 

West Portal



**Fig. 35** 3.04\_West Portal

**Type** Photograph

Description

Author

Archive

Signature

Copyright

Used in:

**Model Reconstruction** 

West Portal




Fig. 36 West Portal Reconstruction Drawing

**Type** Drawn Reconstruction

**Description** Drawn reconstruction based on

photograph records and on-site

survey

**Author** 

**Archive** 

Signature

Copyright

Used in:

**Model Reconstruction** 

West Portal




Fig. 38 2.02 South Portal Entablature

**Type** Photograph

Description

**Author** 

**Archive** 

Signature

Copyright

Used in:

**Model Reconstruction** 

South Portal



Fig. 39 2.03 South Portal's Column Base

Type Used in:

**Description** Model Reconstruction

**Author** South Portal

Archive

Copyright

Signature




Fig. 40 2.01 South Portal

**Type** Photograph

Description

Author

**Archive** 

Signature

Copyright

Used in:

**Model Reconstruction** 

South Portal



Fig. 41 2.04 South Portal's Detail

**Type** Photograph

Description

Author

**Archive** 

Signature

Copyright

Used in:

**Model Reconstruction** 

South Portal




Fig. 42 South Portal Reconstruction Drawing

**Type** Drawn Reconstruction **Used in:** 

**Description** Drawn Reconstruction based on Model Reconstruction

On-site survey South Portal

Author

Archive

**Signature** 

Copyright




Fig. 45 Floor Plan Reconstruction (1973)

| Туре        | Drawing   |
|-------------|---|
| Description | Floor Plan Reconstruction from 1973, unknown author |
| Author      | Unknown   |
| Archive     |   |
| Signature   |   |
| Copyright   | SIPA (Information System for                        |

Architectural Heritage)

Used in:

**Drawn Reconstructions** 

Floor Plan

**Model Reconstruction** 

Floor Plan



Fig. 46 West Elevation Reconstruction Drawing

Signature

Copyright

**Type** Drawn Reconstruction **Used in:** 

**Description** Model Reconstruction

Author West Elevation

Archive




Fig. 48 South Elevation Reconstruction Drawing

**Type** Drawn Reconstruction

**Description** Drawn reconstruction, showing

the project in the current state according to photograph records and on-site survey. In red, the windows used in the building's original stated, before

interventions.

**Author** 

**Archive** 

Signature

Copyright

Used in:

**Model Reconstruction** 

South Elevation



Fig. 50 North Elevation Reconstruction Drawing

**Type** Drawn Reconstruction

**Description** Drawn reconstruction showing

the current state of the building, based on on-site survey and

photograph records.

**Author** José Araújo, Marcelo Odani

**Archive** 

Signature

Copyright

Used in:

**Model Reconstruction** 

North Elevation

Used as area image in:

**Drawn Reconstructions** 

Elevations




Fig. 52 East Elevation Reconstruction Drawing

**Type** Drawn Reconstruction

**Description** Drawn reconstruction of the

bulding's current state, based on photograph records and on-

site survey

**Author** 

**Archive** 

Signature

Copyright

Used in:

**Model Reconstruction** 

**East Elevation** 



Fig. 57 North Portal

Туре

Description

Author

Archive

Signature

Copyright




Fig. 61 West Elevation

Туре

Description

Author

**Archive** 

Signature

Copyright




Fig. 65 Simplification of the previous reconstruction and measurements taken on the survey

**Type** Contemporary drawing / sketch **Used in:** 

**Description** <u>Drawn Reconstructions</u>

**Author** Floor Plan

Archive

Signature

Copyright