



Wall type A

Reconstructed object



Used sources

Bramy\_Nieba\_01



[httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796\\_b1&rlz=1C16CEB\\_enPL1001PL1001&sxsrf=ALiCzsYikMGR\\_C11f9kUD34KD6vemS9nVA1652614594584&tbm=isch&source=i](httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&rlz=1C16CEB_enPL1001PL1001&sxsrf=ALiCzsYikMGR_C11f9kUD34KD6vemS9nVA1652614594584&tbm=isch&source=i)



Argumentation and evaluation of the uncertainty

This is the part of the building that we can still see

04


Wall type B

Reconstructed object



Used sources

Bramy\_Nieba\_03



<httpsbiblioteka.teatrn.pl/dlibrapublicationedition90008action=ChangeMetaLangAction&lang=pl&language=en>




Argumentation and evaluation of the uncertainty

This is the part of the building that we can still see

04


Wall type C

Reconstructed object



Used sources

Bramy\_Nieba\_03



<httpsbiblioteka.teatrnn.pl/dlibrapublicationedition90008action=ChangeMetalangAction&lang=pl&language=en>




Argumentation and evaluation of the uncertainty

This is the part of the building that we can still see

04

Wall type D

Reconstructed object



Used sources

<httpsposhyk.infoplsinagoga-oshmiani>




Argumentation and evaluation of the uncertainty

This is the part of the building that we can still see

04


Roof type A

Reconstructed object



Used sources

Bramy\_Nieba\_04






[httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796\\_b1&rlz=1C16CEB\\_enPL1001PL1001&sxsrf=ALiCzsYikMGR\\_C11f9kUD34KDGvemS9nVA1652614594584&tbn=isch&source=i](httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&rlz=1C16CEB_enPL1001PL1001&sxsrf=ALiCzsYikMGR_C11f9kUD34KDGvemS9nVA1652614594584&tbn=isch&source=i)



Argumentation and evaluation of the uncertainty

This is the part of the building that we can still see


04

Roof type B		
Reconstructed object		
Used sources	Bramy_Nieba_04	
	<a href="httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&amp;rlz=1C16CEB_enPL1001PL1001&amp;sxsrf=ALiCzsYikMGR_C11f9kUD34KD6vemS9nVA1652614594584&amp;tbm=isch&amp;source=i">httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&amp;rlz=1C16CEB_enPL1001PL1001&amp;sxsrf=ALiCzsYikMGR_C11f9kUD34KD6vemS9nVA1652614594584&amp;tbm=isch&amp;source=i</a>	
Argumentation and evaluation of the uncertainty	This is the part of the building that we can still see	04




Roof type C

Reconstruct  
ed object



Used  
sources

Bramy\_Nieba\_04






[httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796\\_b1&rlz=1C16CEB\\_enPL1001PL1001&sxsrf=ALiCzsYikMGR\\_C11f9kUD34KD6vemS9nVA1652614594584&tbm=isch&source=i](httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&rlz=1C16CEB_enPL1001PL1001&sxsrf=ALiCzsYikMGR_C11f9kUD34KD6vemS9nVA1652614594584&tbm=isch&source=i)



Argumentati  
on and  
evaluation  
of the  
uncertainty

This is the part of the building that  
we can still see

04

Domes		
Reconstructed object		
Used sources	<p>Bramy_Nieba_04</p> <p><a href="https://www.google.pl/maps/place/Synagoga+%C5%BCydowska/@54.4250196,25.9337587,3a,90y,284.87h,114.31t/data=!3m8!1e1!3m6!1sAF1Qip0SjUjiXKgBkJ_nstojE5fvfiQy_7PnsiRGP-0e!2e10!3e11!6shttps:%2F%2F1h5.googleusercontent.com%2Fp%2FAF1Qip0SjUjiXKgBkJ_nstojE5fvfiQy_7PnsiRGP-0e%3Dw203-h100-k-no-pi-20-ya148-ro-0-fo100!7i10240!8i5120!4m16!1m8!3m7!1s0x46dc35c575c774af:0xabac80aede42beb!2sSynagoga+%C5%BCydowska!8m2!3d54.424893!4d25.9336653!14m1!1BCgIqAQ!3m6!1s0x46dc35c575c774af:0xabac80aede42beb!8m2!3d54.424893!4d25.9336653!14m1!1BCgIqARICCAI">https://www.google.pl/maps/place/Synagoga+%C5%BCydowska/@54.4250196,25.9337587,3a,90y,284.87h,114.31t/data=!3m8!1e1!3m6!1sAF1Qip0SjUjiXKgBkJ_nstojE5fvfiQy_7PnsiRGP-0e!2e10!3e11!6shttps:%2F%2F1h5.googleusercontent.com%2Fp%2FAF1Qip0SjUjiXKgBkJ_nstojE5fvfiQy_7PnsiRGP-0e%3Dw203-h100-k-no-pi-20-ya148-ro-0-fo100!7i10240!8i5120!4m16!1m8!3m7!1s0x46dc35c575c774af:0xabac80aede42beb!2sSynagoga+%C5%BCydowska!8m2!3d54.424893!4d25.9336653!14m1!1BCgIqAQ!3m6!1s0x46dc35c575c774af:0xabac80aede42beb!8m2!3d54.424893!4d25.9336653!14m1!1BCgIqARICCAI</a></p>	 
Argumentation and evaluation of the uncertainty	This is the part of the building that we can still see	04



Window type A

Reconstructed object



Used sources

Bramy\_Nieba\_03



[httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796\\_b1&rlz=1C16CEB\\_enPL1001PL1001&sxsrf=ALiCzsYikMGR\\_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i](httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&rlz=1C16CEB_enPL1001PL1001&sxsrf=ALiCzsYikMGR_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i)




Argumentation and evaluation of the uncertainty

This is the part of the building that we can still see

04


## Window type B

Reconstructed object



Used sources

Bramy\_Nieba\_03



[httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796\\_b1&rlz=1C16CEB\\_enPL1001PL1001&sxsxf=ALiCzsYikMGR\\_C11f9kUD34K0GvemS9nVA1652614594584&tbn=isch&source=i](httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&rlz=1C16CEB_enPL1001PL1001&sxsxf=ALiCzsYikMGR_C11f9kUD34K0GvemS9nVA1652614594584&tbn=isch&source=i)



Argumentation and evaluation of the uncertainty

This is the part of the building that we can still see

04


# Window type C

Reconstructed object



Used sources

Bramy\_Nieba\_03



[httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796\\_b1&rlz=1C16CEB\\_enPL1001PL1001&sxsrf=ALiCzsYikMGR\\_C11f9kUD34K0GvemS9nVA1652614594584&tbm=isch&source=i](httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&rlz=1C16CEB_enPL1001PL1001&sxsrf=ALiCzsYikMGR_C11f9kUD34K0GvemS9nVA1652614594584&tbm=isch&source=i)



Argumentation and evaluation of the uncertainty


This is the part of the building that we can still see

04



Window type D

Reconstructed object



Used sources

Bramy\_Nieba\_03



[httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796\\_b1&rlz=1C16CEB\\_enPL1001PL1001&sxsrf=ALiCzsYikMGR\\_C11f9kUD34K06vemS9nVA1652614594584&tbm=isch&source=i](httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&rlz=1C16CEB_enPL1001PL1001&sxsrf=ALiCzsYikMGR_C11f9kUD34K06vemS9nVA1652614594584&tbm=isch&source=i)



Argumentation and evaluation of the uncertainty

This is the part of the building that we can still see

04

# Window type E

Reconstructed object




Used sources

[httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796\\_b1&rlz=1C16CEB\\_enPL1001PL1001&sxsrf=ALiCzsYikMGR\\_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i](httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&rlz=1C16CEB_enPL1001PL1001&sxsrf=ALiCzsYikMGR_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i)



Bramy\_Nieba\_04




Argumentation and evaluation of the uncertainty

This is the part of the building that we can still see

04

## Window type F

Reconstructed object




Used sources

[httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796\\_b1&rlz=1C16CEB\\_enPL1001PL1001&sxsrf=ALiCzsYikMGR\\_C11f9kUD34K0GvemS9nVA1652614594584&tbm=isch&source=i](httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&rlz=1C16CEB_enPL1001PL1001&sxsrf=ALiCzsYikMGR_C11f9kUD34K0GvemS9nVA1652614594584&tbm=isch&source=i)



Bramy\_Nieba\_04



Argumentation and evaluation of the uncertainty

This part of the building was reconstructed by deduction based on existing drawings

03



# Window type G

Reconstructed object




Used sources

[httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796\\_b1&rlz=1C16CEB\\_enPL1001PL1001&sxsrf=ALiCzsYikMGR\\_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i](httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&rlz=1C16CEB_enPL1001PL1001&sxsrf=ALiCzsYikMGR_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i)



Bramy\_Nieba\_04




Argumentation and evaluation of the uncertainty

This is the part of the building that we can still see

04

Window type H

Reconstructed object




Used sources

[httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796\\_b1&rlz=1C16CEB\\_enPL1001PL1001&sxsrf=ALiCzsYikMGR\\_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i](httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&rlz=1C16CEB_enPL1001PL1001&sxsrf=ALiCzsYikMGR_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i)



Bramy\_Nieba\_04




Argumentation and evaluation of the uncertainty

This is the part of the building that we can still see

04


# Window type I

Reconstructed object



Used sources

Bramy\_Nieba\_03



<httpsbiblioteka.teatrnn.pl/dlibrapublicationedition90008action=ChangeMetaLangAction&lang=pl&language=en>




Argumentation and evaluation of the uncertainty

This part of the building was reconstructed by deduction based on existing drawings and photos

03

Window type J

Reconstruct  
ed object




Used  
sources

<httpsposhyk.infopolsinagoga-oshmiani>



ZAP\_02



Argumentati  
on and  
evaluation  
of the  
uncertainty

This is the part of the building that  
we can still see

04



Window type K

Reconstruct  
ed object




Used  
sources

<httpsposhyk.infoplsinagoga-oshmiani>



ZAP\_02




Argumentati  
on and  
evaluation  
of the  
uncertainty

This is the part of the building that  
we can still see

04


Window type L

Reconstruct  
ed object



Used  
sources

ZAP\_02



Bramy\_Nieba\_02



Argumentati  
on and  
evaluation  
of the  
uncertainty

This is the part of the building that  
we can still see

04




Window type M

Reconstructed object




Used sources

Bramy\_Nieba\_02






Bramy\_Nieba\_01



Argumentation and evaluation of the uncertainty

This is the part of the building that we can still see

04

Door type A		
Reconstruct ed object		
Used sources	Bramy_Nieba_03	
	Bramy_Nieba_01	
Argumentati on and evaluation of the uncertainty	This part of the building was reconstructed by deduction based on existing drawings	03

Door type B

Reconstructed object




Used sources

[https://www.google.com/search?q=ashmyany-sinagoga-synagoga-1416-1574076796\\_b1&rlz=1C16CEB\\_enPL1001PL1001&sxsrf=ALiCzsYikMGR\\_C11f9kUD34KD6vemS9nVA1652614594584&tbm=isch&source=i](https://www.google.com/search?q=ashmyany-sinagoga-synagoga-1416-1574076796_b1&rlz=1C16CEB_enPL1001PL1001&sxsrf=ALiCzsYikMGR_C11f9kUD34KD6vemS9nVA1652614594584&tbm=isch&source=i)



ZAP\_01



Argumentation and evaluation of the uncertainty

This part of the building was reconstructed by deduction based on existing drawings and photos

03


Door type C

Reconstructed object




Used sources

Bramy\_Nieba\_01



Bramy\_Nieba\_04



Argumentation and evaluation of the uncertainty

This part of the building was reconstructed by deduction based on existing drawings

03


Door type D

Reconstruct  
ed object




Used  
sources

Bramy\_Nieba\_01



Bramy\_Nieba\_04



Argumentati  
on and  
evaluation  
of the  
uncertainty

This is the part of the building that  
we can still see

04

Pilaster type A

Reconstruct  
ed object



Used  
sources

Bramy\_Nieba\_03



[httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796\\_b1&rlz=1C16CEB\\_enPL1001PL1001&sxsrf=ALiCzsYikMGR\\_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i](httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&rlz=1C16CEB_enPL1001PL1001&sxsrf=ALiCzsYikMGR_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i)






Argumentati  
on and  
evaluation  
of the  
uncertainty

This is the part of the building that we can still see

04



Pilaster type B		
Reconstruct ed object		
Used sources	<p><a href="httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&amp;rlz=1C16CEB_enPL1001PL1001&amp;sxsrf=ALiCzsYikMGR_C11f9kUD34KD6vemS9nVA1652614594584&amp;tbm=isch&amp;source=i">httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&amp;rlz=1C16CEB_enPL1001PL1001&amp;sxsrf=ALiCzsYikMGR_C11f9kUD34KD6vemS9nVA1652614594584&amp;tbm=isch&amp;source=i</a></p>	
	Bramy_Nieba_01	
Argumentati on and evaluation of the uncertainty	This is the part of the building that we can still see	04

# Pilaster type C

Reconstructed object



Used sources

Bramy\_Nieba\_03






[httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796\\_b1&rlz=1C16CEB\\_enPL1001PL1001&sxsrf=ALiCzsYikMGR\\_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i](httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&rlz=1C16CEB_enPL1001PL1001&sxsrf=ALiCzsYikMGR_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i)









Argumentation and evaluation of the uncertainty




This is the part of the building that we can still see

04

Pilaster type D		
Reconstruct ed object		
Used sources	Bramy_Nieba_04	
	Bramy_Nieba_01	
Argumentati on and evaluation of the uncertainty	This is the part of the building that we can still see	04

Pilaster type E		
<p>Reconstruct ed object</p>		
<p>Used sources</p>	<p>Bramy_Nieba_02</p>	
	<p>Bramy_Nieba_01</p>	
<p>Argumentati on and evaluation of the uncertainty</p>	<p>This is the part of the building that we can still see</p>	<p>04</p>


Floor type A		
Reconstruct ed object		
Used sources	Bramy_Nieba_04	
	Bramy_Nieba_02	
Argumentati on and evaluation of the uncertainty	This is the part of the building that we can still see	04

Floor type B		
<p>Reconstruct ed object</p>		
<p>Used sources</p>	<p>Bramy_Nieba_04</p>	
	<p>Bramy_Nieba_02</p>	
<p>Argumentati on and evaluation of the uncertainty</p>	<p>This is the part of the building that we can still see</p>	<p>04</p>




Celling type A

Reconstruct  
ed object




Used  
sources

Bramy\_Nieba\_04






Bramy\_Nieba\_02









Argumentati  
on and  
evaluation  
of the  
uncertainty

This is the part of the building that  
we can still see

04


Celling type B		
Reconstruct ed object		
Used sources	Bramy_Nieba_04	
	Bramy_Nieba_02	
Argumentati on and evaluation of the uncertainty	This is the part of the building that we can still see	04

Stairs		
Reconstruct ed object		
Used sources	Bramy_Nieba_04	
	Bramy_Nieba_01	
Argumentati on and evaluation of the uncertainty	<p>This part of the building was reconstructed by deduction based on existing drawings</p>	03

Bemas		
Reconstruct ed object		
Used sources	Bramy_Nieba_01	
	ZAP_01	
Argumentati on and evaluation of the uncertainty	<p>This part of the building was reconstructed by deduction based on existing drawings</p>	03

# Cornice type A

Reconstructed object



Used sources

[httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796\\_b1&rlz=1C1GCEB\\_enPL1001PL1001&sxsrf=ALiCzYikMGR\\_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i](httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&rlz=1C1GCEB_enPL1001PL1001&sxsrf=ALiCzYikMGR_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i)



Bramy\_Nieba\_03



Argumentation and evaluation of the uncertainty


This is the part of the building that we can still see

04



# Cornice type B

Reconstructed object



Used sources

[https://www.google.com/search?q=ashmyany-sinagoga-synagoga-1416-1574076796\\_b1&rlz=1C16CEB\\_enPL1001PL1001&sxsrf=ALiCzsYikMGR\\_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i](https://www.google.com/search?q=ashmyany-sinagoga-synagoga-1416-1574076796_b1&rlz=1C16CEB_enPL1001PL1001&sxsrf=ALiCzsYikMGR_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i)



Bramy\_Nieba\_03




Argumentation and evaluation of the uncertainty

This is the part of the building that we can still see

04

Cornice type C

Reconstructed object



Used sources

[httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796\\_b1&rlz=1C16CEB\\_enPL1001PL1001&sxsrf=ALiCzsYikMGR\\_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i](httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&rlz=1C16CEB_enPL1001PL1001&sxsrf=ALiCzsYikMGR_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i)



Argumentation and evaluation of the uncertainty

This is the part of the building that we can still see

04

## Cornice type D

Reconstructed object



Used sources

[httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796\\_b1&rlz=1C16CEB\\_enPL1001PL1001&sxsrf=ALiCzsYikMGR\\_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i](httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&rlz=1C16CEB_enPL1001PL1001&sxsrf=ALiCzsYikMGR_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i)




Argumentation and evaluation of the uncertainty

This is the part of the building that we can still see

04

Cornice type E

Reconstruct  
ed object




Used  
sources

[httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796\\_b1&rlz=1C16CEB\\_enPL1001PL1001&sxsrf=ALiCzsYikMGR\\_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i](httpswww.google.comsearchq=ashmyany-sinagoga-synagoga-1416-1574076796_b1&rlz=1C16CEB_enPL1001PL1001&sxsrf=ALiCzsYikMGR_C11f9kUD34KDGvemS9nVA1652614594584&tbm=isch&source=i)



Bramy\_Nieba\_03




Argumentati  
on and  
evaluation  
of the  
uncertainty

This is the part of the building that  
we can still see

04


Cornice type F

Reconstructed object




Used sources

Bramy\_Nieba\_04



Bramy\_Nieba\_02



Argumentation and evaluation of the uncertainty

This is the part of the building that we can still see

04